



航模无刷电机绕线方法

6N8P




6N10P




9N4P

9N10PVA




9N10PVI

9NGrund




9Nlangcw

12N14PLRK5




12N14Pvol1278cw

12N16P




18N20P

18N24P



24N22P



24N28P

